



DETAIL 1 HEAD



DETAIL 2 HORIZONTAL MULLION


NO CABLE ROUTING IN SILL




DETAIL 3

NOTES:

- INSTALLER TO PROVIDE GROMMETS AT ALL FRAME PENETRATIONS WHERE POSSIBLE TO AVOID CABLE DAMAGE.
- INSTALLER TO LABEL IGU CABLES WITH IGU NAME TO WHICH IT IS CONNECTED.
- WHEN GLAZING POCKET CANNOT ACCOMMODATE IGU/SWC, INCORPORATE SERVICE LOOP INTO IGU CABLING. MAKE CONNECTION TO SWC AS YOU ARE GLAZING AND PUSH CONNECTOR THROUGH HOLE AND INTO MULLION.
- 4. NO WIRE ROUTING IN SILL.



DETAIL 4 LEFT JAMB



DETAIL 5 VERTICAL MULLION



VIEW, INC.® 195 SOUTH MILPITAS BLVD. MILPITAS, CA 95035 v. 408/263.9200 www.viewglass.com

SUGGESTED IGU CABLE ROUTING — TYPICAL ELEVATION

SUGGESTED SMART

(SWC) ORIENTATIONS -

WINDOW CONNECTOR

SCALE: NONE

VIEW INC. CONFIDENTIAL: THIS DOCUMENT AND THE INFORMATION CONTAINED IN IT ARE CONFIDENTIAL, AND CANNOT BE COPIED OR DISCLOSED IN WHOLE OR IN PART WITHOUT THE EXPRESS WRITTEN CONSENT OF VIEW, INC.®